

RUBBERLOC

Conveyor belt repair system



FROM ENVIROPEEL



AGGREGATE PRODUCTION



A large aggregate producer in Indiana had a long through hole in an incline belt. The belt transported material from the primary crusher in which large chunks of limestone were broken into more manageable pieces. The damage was producing a lot of spillage and the tear was getting bigger every day. Rubberloc was used to repair the damage in just a few hours and the belt was returned to service. The repair was still intact when the belt was replaced during routine maintenance nearly four years later.



The photos of the repaired belt, shown left, were taken eighteen months after the repair was completed.



www.rubberloc.com

info@rubberloc.com 1-317-631-9109